


TO WHOM SO EVER IT MAY CONCERN

BUILDING SAFETY CERTIFICATE

It is certified that the building of Maxx International School V.P.O. Jia Tehsil Bhunter Distt. Kullu HP has been inspected by the Assistant Engineer Bhuntar Sub Division HPPWD Bhuntar, as per his visual inspection the building seems to be safe to run school classes for the academic year 2025-26 under normal condition. However structural stability cannot be ascertained due to non-availability of structural design, drawings and IS specification required for the building construction. This certificate is being issued purely on the basis of visual inspection and issuance of this certificate does not confer any legal and financial liabilities on the issuer please.



**Executive Engineer,
Kullu Division,
HPPWD Kullu.**

No.PW/KD/WA-I/Building/2024:- 15397-98


Dated:- 19-3-25

Copy to the Assistant Engineer Bhuntar Sub Division HPPWD Bhuntar with reference to his office letter No. PW/BSD/Bldg.Safety Certificate/2025- 1206 dated 07.03.2025 for information and necessary action.

Copy to the Principal Maxx International School V.P.O. Jia Tehsil Bhunter Distt. Kullu HP.


**Executive Engineer,
Kullu Division,
HPPWD Kullu.**

Building P-442
Dated:-19.03.2025


**Chairman
S.J.S. Educational Society
VPO Jia, Distt. Kullu (H.P.)**


**Principal
Maxx International School
VPO- Jia, Kullu (H.P.)**